


Green Chemistry & Commerce Council Moving Business Toward Safer Alternatives

A GC3 Retailer Webinar Series



Eliminating Restricted Substances in the Apparel and Footwear Supply Chain: The AFIRM Supplier Toolkit




Nathaniel Sponsler, Manager-Product Regulations, Gap Inc.

Webinar Discussion Instructions

• Due to the number of participants on the Webinar, all lines will be muted.

- If you wish to ask a question, please type your question in the Q&A box located in the drop down control panel at the top of the screen
- All questions will be answered at the end of the presentation.



Introduction to the AFIRM Supplier Toolkit

Nathaniel Sponsler Gap Inc.







































Who is AFIRM?

- Apparel & Footwear International RSL Management Group
- Established in July 2004
- Original Member Companies:
 - adidas
 - C&A
 - Gap
 - Levi
 - Nike
 - Marks and Spencer







































AFIRM Mission

 To reduce the use and impact of harmful substances in the apparel and footwear supply chain







































Current Members



- adidas-Group
- BESTSELLER
- Carhartt
- ESPRIT
- Gap, Inc.
- Gymboree
- H&M
- Hugo Boss
- J.CREW

- Levi Strauss & Co.
- New Balance
- Nike
- Pentland
- PUMA
- s.Oliver
- Warnaco
- Wolverine World Wide
- VF Corporation








































What Exactly is the Toolkit?

 Collection of resources to help the global apparel/footwear supply chain understand and reduce the use and impact of harmful substances







































AFIRM Toolkit History

- First version published October 2008
- Supplier Feedback:
 - Seemed geared toward brands
 - More technical information and examples requested
 - Request for AFIRM combined RSL to meet all brand requirements







































New 2011 AFIRM Supplier Toolkit

- Published November 2011
- Responds to Supplier Feedback
 - Geared toward suppliers
 - More detailed information on more chemicals
 - Improved formatting and internal links
- Available in Chinese & Vietnamese
 - More languages planned in 2013







































New 2011 AFIRM Supplier Toolkit

- Key Additions
 - RSL Failures with corrective action examples in simple format
 - Detailed Chemical Guidance Document with full Index
- Resources available for all levels of technical expertise









































1.	Introd	<u>испоп</u>	1
	D	efinition of Restricted Substances	1
	W	hy Substances Are Restricted	1
	Pu	urpose of the RSL & Why It Is Important to Suppliers	1
2.	Restric	cted Substances List	2
3.	Where	e Are the Risks?	2
	FI	owchart for Understanding Chemical Risks	3
	Ba	ackground on Restricted Substances	4
4.	Educat	te the Supply Chain	12
5.	Labora	atory RSL Testing	13
6.	RSL Im	plementation	14
7.	Appen	dices	15
	Α.	Glossary of Terms	16
	В.	Factory Management Plan	17
	C.	Model Brand Program Protocol for Testing Clothing	20
	D.	Best Practices to Avoid RSL Issues	26
	E.	RSL Failures & Corrective Action Examples	30
	F.	Detailed Chemical Guidance Document	31
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations	32
	Н.	RSL Failure Resolution Form	33
	1.	Screen Printing & Applications/Finishing Best Practices	34
	J.	AFIRM Frequently Asked Questions (FAQ)	35
	K.	Benefits of Water-Based Polyurethane	47
	L.	Additional Online Resources	48





































1.	Introd	uction	1
	<u>D</u>	efinition of Restricted Substances	1
	V	/hy Substances Are Restricted	1
	<u>P</u>	urpose of the RSL & Why It Is Important to Suppliers	1
	Restri	ted Substances List	2
3.	When	Are the Risks?	2
	<u>E</u>	owchart for Understanding Chemical Risks	3
	<u>B</u>	ackground on Restricted Substances	4
4.	Educa	te the Supply Chain	12
5.	Labor	tory RSL Testing	13
6.	RSL In	plementation	14
7.	Apper	dices	15
	A.	Glossary of Terms	16
	В.	Factory Management Plan	17
	C.	Model Brand Program Protocol for Testing Clothing	20
	D.	Best Practices to Avoid RSL Issues	26
	E.	RSL Failures & Corrective Action Examples	30
	F.	Detailed Chemical Guidance Document	31
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations	32
	Н.	RSL Failure Resolution Form	33
	I.	Screen Printing & Applications/Finishing Best Practices	34
	J.	AFIRM Frequently Asked Questions (FAQ)	35
	K.	Benefits of Water-Based Polyurethane	47
	L.	Additional Online Resources	48

Where are the risks?

	Natural fibres	Synthetic fibres	Natural and synthetic blends	Artificial leather with fibre backing	Natural leather	Plastic, rubber, paint, and coatings	Natural materials (e.g., paper, wood)	Metal	Fusing, padding, feather, and down
AP / APEO	٠	٠	•	•	٠	•			•
AZO	•	•	•		٠				
Cationic Surfactant		٠	•						
Chlorinated Organic Carriers		•	•						
Chloroparaffins (SCCP and MCCP)					•				
Chromium VI					•			9	
Disperse Dyes		•	•						
Flame Retardants				If speci	al finish		,		•
Formaldehyde	•	•	•		•	•	•		•
Metals, extractable	•		•		٠				
Metals, total				•		•		•	2
Nickel release								•	
Perflurooctane Sulfonate (PFOS) and PFOS-related substances Perfluorooctane Acid (PFOA) and its salts				If wate	r-repelle	ent finis	h		~
pH-value	•		•						
Phenols	•		•		•		•		•
Phthalates				•		•			
Polycyclic Aromatic Hydrocarbons (PAHs)						•			
PVC				•		•		60	
Tin Organic Coumpounds				•		•			





































1.	Introd	uction
	<u>D</u>	efinition of Restricted Substances
	<u>V</u>	/hy Substances Are Restricted
	<u>P</u>	urpose of the RSL & Why It Is Important to Suppliers
2.	Restri	ted Substances List
3.	When	Are the Risks?
	<u> </u>	owchart for Understanding Chemical Risks
2	В	ackground on Restricted Substances
4.	Educa	te the Supply Chain1
5.	Labor	tory RSL Testing1
6.	RSL In	plementation
7.	Apper	<u>dices</u> 1
	A.	Glossary of Terms
	В.	Factory Management Plan
	C.	Model Brand Program Protocol for Testing Clothing2
	D.	Best Practices to Avoid RSL Issues2
	E.	RSL Failures & Corrective Action Examples
	F.	Detailed Chemical Guidance Document3
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations3
	Н.	RSL Failure Resolution Form3
	I.	Screen Printing & Applications/Finishing Best Practices
	J.	AFIRM Frequently Asked Questions (FAQ)3
	K.	Benefits of Water-Based Polyurethane4
	L.	Additional Online Resources4

Background on Restricted Substances

RESTRICTED SUBSTANCES	DESCRIPTION & WHERE THEY MAY BE FOUND
	APEOS are non-ionic surfactants including NPEOs, OPEOs, NP, and OP. NPEOs and OPEOs degrade into NP and OP, respectively. APEOs can be used as or found in:
Alkyphenol Ethoxylates (APEOs) / Alkylphenols (AP) Nonylphenol Ethoxylates (NPEO) Octylphenol Ethoxylates (OPEO) Nonylphenol (NP) Octylphenol (OP)	 Detergents Scouring agents Wetting agents Softeners Emulsifier/dispersing agents for dyes and prints Impregnating agents Degreasing agents for leather Leather Finishing De-gumming for silk production Dyes and pigment preparations Polyester padding Down/feather fillings







































1.	Introd	<u>uction</u>	1		
	<u>Definition of Restricted Substances</u>				
	W	/hy Substances Are Restricted	1		
	Pi	urpose of the RSL & Why It Is Important to Suppliers			
2.		cted Substances List			
3.		e Are the Risks?			
	Fl	owchart for Understanding Chemical Risks			
		ackground on Restricted Substances			
4.		te the Supply Chain			
5.		atory RSL Testing			
6.		plementation			
7.		idices			
	. A.				
9	В.	Factory Management Plan			
	С.	Model Brand Program Protocol for Testing Clothing			
	-				
	D.	Best Practices to Avoid RSL Issues			
	Ε.	RSL Failures & Corrective Action Examples			
	F.	Detailed Chemical Guidance Document			
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations			
	Н.	RSL Failure Resolution Form			
	l.	Screen Printing & Applications/Finishing Best Practices			
	J.	AFIRM Frequently Asked Questions (FAQ)			
	K.	Benefits of Water-Based Polyurethane	47		
	L.	Additional Online Resources	48		

Appendix B - Factory Management Plan

Data Management

- Access to RSL data throughout the supply chain is a key component in management strategy for the RSL. Strategic testing of materials is critical for streamlining RSL management.
- Describe how you manage data you collect from sample analysis/testing and how you share that information with your partners
 - · Do you have a database for all testing data?
 - · Do you send this data for management review on a regular basis?
 - · Do you identify suppliers with repeated failures and put them on notice?

Tracking Time Table

Set up a time table which identifies your RSL Plan of each year. Some items must be included, such as: Four deadlines of reviewing of your RSL Data trend; One training/meeting on RSL to your vendors; Summary of your RSL tracking from Purchasing at the end of the year.

Example:

Progress	Target Date	Finish Date
Complete RSL Plan and present to factory management	1/20/13	
Discuss RSL Plan with vendors	2/20/13	
Set up the RSL Action Plan Schedule	4/20/13	
Prepare material for RSL testing	5/20/13	
Finish RSL testing	6/20/13	
Review RSL data trend with vendors	7/20/13	
Review and revise RSL plan for continuous improvement	8/20/13	



































1.	Introd	uction			
	Definition of Restricted Substances				
	W	/hy Substances Are Restricted1			
	Pu	urpose of the RSL & Why It Is Important to Suppliers1			
2.	Restric	cted Substances List			
3.	Where	Are the Risks?			
	Fl	owchart for Understanding Chemical Risks			
	Bá	ackground on Restricted Substances4			
4.	Educat	te the Supply Chain12			
5.	Labora	atory RSL Testing13			
6.	RSL Im	plementation14			
7.	Appen	<u>dices</u> 1			
	A.	Glossary of Terms			
	В.	Factory Management Plan			
	C.	Model Brand Program Protocol for Testing Clothing20			
_	D.	Best Practices to Avoid RSL Issues			
	E.	RSL Failures & Corrective Action Examples			
	F.	Detailed Chemical Guidance Document			
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations32			
	H.	RSL Failure Resolution Form			
	I.	Screen Printing & Applications/Finishing Best Practices			
	J.	AFIRM Frequently Asked Questions (FAQ)			
	K.	Benefits of Water-Based Polyurethane4			
	L.	Additional Online Resources48			

Appendix D – Best Practices to Avoid RSL Issues

	Restricted Substance	Manufacturing Technology that Could Introduce The Substance	Steps to Avoid Restricted Substance in Finished Products
		Resins to prevent shrinkage	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
		Resins to prevent wrinkling	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
	Formaldehyde	Resins to permanently include wrinkles	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
		Discharge Printing	Water based discharge printing systems rely on Zinc Formaldehyde Sulfonate (ZFS). Discharge prints must be used according to manufacturers instructions to meet adult formaldehyde requirements.
Natural Fibers (cotton, rayon, wool, hemp, etc.)		Pigment print binder	Use formaldehyde free binders; Use low formaldehyde binders & fully cure to chemical supplier specifications to remove free formaldehyde.
	Heavy metals (mercury,	Dye stuff	Use dyestuff from internationally recognized dye stuff suppliers with commitments to chemical compliance.
	lead, cadmium)	Pigment prints	Use pigments from internationally recognized dye stuff suppliers with commitments to chemical compliance.
	Azo amines	Dye stuff	Use dyestuff from internationally recognized dye stuff suppliers with commitments to chemical compliance.
		Pigment prints	Azo structures in pigments can cleave into one of the harmful amines. With low solubility the consumer risk is minimal, but GC/MS will detect amines. LC/MS can be used for proper confirmation. Check with ETAD www.etad.com for a list of pigments that pose this risk.
	Formaldehyde	Resins to prevent shrinkage	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
		Resins to prevent wrinkling	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
		Resins to permanently include wrinkles	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
		Cross linking agent in coating processes	Use formaldehyde free resins; Use low formaldehyde resins & fully cure to chemical supplier specifications to remove free formaldehyde.
Synthetic Fibers (polyester,		Dye stuff	Use dyestuff from internationally recognized dye stuff suppliers with commitments to chemical compliance.
nylon, acetate, acrylic, etc.)	Heavy metals (mercury, lead, cadmium)	Stabilizer	More likely in molded plastics than fibers, but cadmium should not be used as a stabilizer.
		Polymer extrusion contamination	Heavy metals such as lead, cadmium and mercury are not likely intentionally used in polymer extrusion, but could be present due to contamination.
	Disperse dyes	Dye stuff	Use dyestuff from internationally recognized dye stuff suppliers with commitments to chemical compliance. Orange 37/76 is the most common failure and is commonly found in dark colors which use Orange 37/76 in the recipe.
	Azo dyes	Dye stuff	Synthetic fibers with a PU or fluorinated coating may give a false positive for azo amines if tested using GC/MS. LC/MS can be used for confirmation. Use dyestuff from internationally recognized dye stuff suppliers with commitments to chemical compliance.



































1.	Introd	uction1				
	Definition of Restricted Substances1					
	Why Substances Are Restricted1					
	<u>P</u> (urpose of the RSL & Why It Is Important to Suppliers1				
2.	Restric	sted Substances List2				
3.	Where	e Are the Risks?2				
	<u>Fl</u>	owchart for Understanding Chemical Risks3				
	Bi	ackground on Restricted Substances4				
4.	Educa	te the Supply Chain				
5.	Labora	story RSL Testing				
6.	RSL Im	plementation				
7.	Appen	dices				
	A.	Glossary of Terms				
	В.	Factory Management Plan				
	C.	Model Brand Program Protocol for Testing Clothing				
	D.	Best Practices to Avoid RSL Issues				
2	E.	RSL Failures & Corrective Action Examples				
	F.	Detailed Chemical Guidance Document31				
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations32				
	Н.	RSL Failure Resolution Form				
	I.	Screen Printing & Applications/Finishing Best Practices				
	J.	AFIRM Frequently Asked Questions (FAQ)35				
	K.	Benefits of Water-Based Polyurethane				
	L.	Additional Online Resources				

Appendix E – RSL Corrective Actions







































1.	Introd	uction	1		
	Definition of Restricted Substances				
	Why Substances Are Restricted				
	<u>P</u> (urpose of the RSL & Why It Is Important to Suppliers	1		
2.	Restric	ted Substances List	2		
3.	Where	Are the Risks?	2		
	<u>Fl</u>	owchart for Understanding Chemical Risks	3		
	B	ackground on Restricted Substances	4		
4.	Educa	te the Supply Chain	12		
5.	Labora	story RSL Testing	13		
6.	RSL Im	plementation	14		
7.	Appen	dices	15		
	A.	Glossary of Terms	16		
	В.	Factory Management Plan	17		
	C.	Model Brand Program Protocol for Testing Clothing	20		
	D.	Best Practices to Avoid RSL Issues	26		
	E.	RSL Failures & Corrective Action Examples	30		
	F.	Detailed Chemical Guidance Document	31		
	G.	$\underline{\text{Material Safety Data Sheet (MSDS) Examples and Explanations}}$	32		
	Н.	RSL Failure Resolution Form	33		
	l.	Screen Printing & Applications/Finishing Best Practices	34		
	J.	AFIRM Frequently Asked Questions (FAQ)	35		
	K.	Benefits of Water-Based Polyurethane	47		
	1.	Additional Online Resources	48		

Appendix E – RSL Corrective Actions

Restricted Substance	Issue	Slide #
Formaldehyde	Discharge Printing	2
Formaldehyde	Cap Stiffener	5
Formaldehyde	Wrinkle Effect	8
Formaldehyde	Pigment Print	11
Formaldehyde	Recipe Calculation	14
Formaldehyde	Leather Tanning	17
Aromatic Amines	Drawcord Dyestuff	21
Heavy Metals - Cadmium	PVC pigment	23
Heavy Metals - Lead	Paint pigment	26
Heavy Metals - Lead	Polyurethane coating	29
Heavy Metals - Lead	Heat transfer	32
Heavy Metals - Chromium	Metalized Dye	34
Heavy Metals - Mercury	Solvent cleaner	36
Phthalates - DEHP	Spray adhesive	38
Phthalates - alternative	Solvent plasticizer	41
APEO	Scouring agent	44
APEO	Fiber board emulsion	47
APEO	Leather degreasing	49
Organotins	Adhesive heat stabilizer	51
Miscellaneous - Phenol	Adhesive contamination	54
Miscellaneous - PAH	Rubber formula	57
Miscellaneous - PFOA	Non-wicking treatment	60
Miscellaneous - VOC	Solvent contamination	63
Miscellaneous - Phenol	Print paste thickener	65
Miscellaneous - VOC	Yarn lubricant	67
Disperse Dyes	Woven label	69






































1.	Introd	uction	1	
	Definition of Restricted Substances			
	W	/hy Substances Are Restricted	1	
	P	urpose of the RSL & Why It Is Important to Suppliers	1	
2.	Restric	cted Substances List	2	
3.	Where	Are the Risks?	2	
	<u>Fl</u>	owchart for Understanding Chemical Risks	3	
	Bi	ackground on Restricted Substances	4	
4.	Educa	te the Supply Chain	12	
5.	Labora	story RSL Testing	13	
6.	RSL Im	plementation	14	
7.	Appen	dices	15	
	A.	Glossary of Terms	16	
	В.	Factory Management Plan	17	
	C.	Model Brand Program Protocol for Testing Clothing	20	
	D.	Best Practices to Avoid RSL Issues	26	
2	E.	RSL Failures & Corrective Action Examples	30	
	F.	Detailed Chemical Guidance Document	31	
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations	32	
	Н.	RSL Failure Resolution Form	33	
	l.	Screen Printing & Applications/Finishing Best Practices	34	
	J.	AFIRM Frequently Asked Questions (FAQ)		
	K.	Benefits of Water-Based Polyurethane	47	
	L.	Additional Online Resources		

Appendix E – RSL Corrective Actions

Problem #2

- Consumer complaints that the flip flops had sticky feeling and were removing lacquer finish on wood floors
- Laboratory analysis detected tributycitrate (TBC) instead of ATBC as manufacturer claimed
- TBC is a known solvent for decoating furniture
- Manufacturer substituted TBC as a cheaper alternative for ATBC





Phthalates





































1.	Introd	<u>uction</u> 1		
	Definition of Restricted Substances			
	Why Substances Are Restricted			
	Pi	urpose of the RSL & Why It Is Important to Suppliers1		
2.	Restric	cted Substances List		
3.	Where	e Are the Risks?		
	Fl	owchart for Understanding Chemical Risks3		
		ackground on Restricted Substances4		
4.		te the Supply Chain		
5.		atory RSL Testing		
6.		plementation		
7.		dices		
′.	<u>лърсп</u> А.	Glossary of Terms		
	В.	Factory Management Plan		
	-			
	C.	Model Brand Program Protocol for Testing Clothing20		
	D.	Best Practices to Avoid RSL Issues		
	E.	RSL Failures & Corrective Action Examples		
_	F.	<u>Detailed Chemical Guidance Document</u> 31		
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations32		
	Н.	RSL Failure Resolution Form		
	I.	Screen Printing & Applications/Finishing Best Practices34		
	J.	AFIRM Frequently Asked Questions (FAQ)35		
	K.	Benefits of Water-Based Polyurethane47		
	L.	Additional Online Resources		

Appendix F – Detailed Chemical Guidance Document



CHEMICAL GUIDANCE DOCUMENT

Dr. Dieter Sedlak (Dipl. Chemc.) +49 (821) 56 97 96-10 d.sedlak@mts-germany.eu

Table of Contents

Section	Section P		
1 Introdu	ction	6	Ē
1.1 Back	ground on Textile Industry	6	
2 Textile I	Industry: Basic Raw Materials	14	4
2.1 Texti	le Raw Materials	14	
2.2 Natu	ral Fibers		
2.2.1	Wool	15	
2.2.2	Cotton	16	
2.2.3	Silk	19	
224	Elav	10	











HUGO

























1.	1. <u>Introduction</u>				
	Definition of Restricted Substances				
	Why Substances Are Restricted				
	P	urpose of the RSL & Why It Is Important to Suppliers1	Ĺ		
2.	Restric	cted Substances List	2		
3.	Where	Are the Risks?	2		
	<u>Fl</u>	owchart for Understanding Chemical Risks	3		
	B	ackground on Restricted Substances4	1		
4.	Educa	te the Supply Chain)		
5.	Labora	atory RSL Testing1	3		
6.	RSL Im	plementation	4		
7.	Appen	<u>dices</u> 1	5		
	A.	Glossary of Terms	ó		
	В.	Factory Management Plan	1		
	C.	Model Brand Program Protocol for Testing Clothing20)		
	D.	Best Practices to Avoid RSL Issues	ô		
	Ε.	RSL Failures & Corrective Action Examples)		
2	F.	Detailed Chemical Guidance Document	l		
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations 32	2		
	Н.	RSL Failure Resolution Form	3		
	l.	Screen Printing & Applications/Finishing Best Practices	1		
	J.	AFIRM Frequently Asked Questions (FAQ)35	5		
	K.	Benefits of Water-Based Polyurethane47			
	L.	Additional Online Resources			

Appendix F – Detailed Chemical Guidance Document

6.2.4.1 Unintended Oxidation of Chromium III to Chromium VI in Leather and Leather Products

Chromium (VI) is not intended or used in the production process and must be regarded as cross contamination by avoidable oxidation of trivalent Chromium to hexavalent chromium, which is a harmful substance. Oxidation of Cr (III) into Cr (VI) normally occurs in presence of strong oxidation agent in acid environment but it can also take place in presence of mild oxidation agents at high pH. In leather processing neutralization is a stage where such conditions are created; therefore, leather and leather products sometimes contain Cr (VI) although only chromium compounds in the form of Cr (III) were used in the tanning process.

Also the hydrogen peroxide left over from the first step of tanning will contribute to unintended oxidation of Cr (III) to Cr (VI).



































1.	Introduction		
	Definition of Restricted Substances		
	W	/hy Substances Are Restricted	1
	<u>P</u> (urpose of the RSL & Why It Is Important to Suppliers	
2.		cted Substances List	
3.		e Are the Risks?	
		owchart for Understanding Chemical Risks	
		ackground on Restricted Substances	
4.		te the Supply Chain	
5.			
6.			
-		•	
7.	Appen	<u>dices</u>	
	A.	Glossary of Terms	16
	В.	Factory Management Plan	17
	C.	Model Brand Program Protocol for Testing Clothing	20
	D.	Best Practices to Avoid RSL Issues	26
	Ε.	RSL Failures & Corrective Action Examples	3(
2	F.	Detailed Chemical Guidance Document	3:
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations	32
	Н.	RSL Failure Resolution Form	
	I.	Screen Printing & Applications/Finishing Best Practices	34
	J.	AFIRM Frequently Asked Questions (FAQ)	
	К.	Benefits of Water-Based Polyurethane	
	L.	Additional Online Resources	
	L.	Additional Office Resources	40

Appendix F – Detailed Chemical Guidance Document

AFIRM Chemical Guidance Document

9 Index

Α

acaricides, 16
acetate, 17, **22**, 38, 40, 54, 65
acetic acid, 11, 13, 22, 31, 32, 34, 40, 41, 55, 58, 82, 88, 90, 91, 92, 95, 105, 106, 108, 113
acetic acid-(2-ethoxyethyl)-ester, 113
acetone, 22, 139

acrylamide, 13, 43, 45, 48, 115 acrylate, 42, 43, 45, 47, 48, 49, 54, 113

acrolein (2-propenoic aldehyde), 113

acrylic acid, 17, 18, 47, 48, 113, 116

acrylonitrile, 20, 43, 45, 48, 88, 90, 115





































1.	Introd	<u>uction</u> 1	
	<u>D</u>	efinition of Restricted Substances1	
	V	/hy Substances Are Restricted1	
	<u>P</u>	urpose of the RSL & Why It Is Important to Suppliers1	
2.	Restri	cted Substances List2	
3.	Where	e Are the Risks?2	
	<u>Fl</u>	owchart for Understanding Chemical Risks3	
	<u>B</u>	ackground on Restricted Substances4	
4.	Educa	te the Supply Chain	
5.	Labora	atory RSL Testing	
6.	RSL Im	plementation	
7.	Appendices		
	Α.	Glossary of Terms	
	В.	Factory Management Plan	
	C.	Model Brand Program Protocol for Testing Clothing20	
	D.	Best Practices to Avoid RSL Issues	
	E.	RSL Failures & Corrective Action Examples	
	▲ F.	Detailed Chemical Guidance Document31	
2	G.	Material Safety Data Sheet (MSDS) Examples and Explanations32	
	Н.	RSL Failure Resolution Form	
	I.	Screen Printing & Applications/Finishing Best Practices	
	 J.	AFIRM Frequently Asked Questions (FAQ)	
	К.	Benefits of Water-Based Polyurethane	
	L.	Additional Online Resources	
	L	Traditional Office Resources	

Appendix G – MSDS Examples and Explanations

Safety Data Sheet

according to Regulation (EC) No. 1907/2006 (REACH)

Trade name:

Material.-No.: Version: 1.0 / EN Print date: Specification: Page 02 of 15 Revision date:

2. HAZARDS IDENTIFICATION

Classification:

Other Hazards

Informations pertaining to special dangers for human and environment:

Adverse physicochemical effect(s):
Adverse human health effect(s) and symptom(s):

Adverse environmental effect(s):

Other adverse hazard(s):

COMPOSITION/INFORMATION ON INGREDIENTS,

Chemical characterization (substance):

CAS.-No.:

EC-No. INDEX-No.:

Purity:

Synonyme(s):

Stabilizer(s):

Hazard(ous) impurity(ies):

Kommentar [HA8]: Distinguish clearly between preparations which are classified as dangerous and preparations which are not classified as dangerous according to Directive 1990/M/IFC

Describe the most important adverse physicochemical, human health and environmental effects and symptoms relating to the uses and possible misuses of the substance or preparation that can reasonably be foreseen.

Kommentar [HA9]: The classification of the substance shall be consistent with the classification provided to the classification and labelling inventory according to Title XI.

Kommentar [HA10]:

Describe the most important adverse physicochemical, human health and environmental effects and symptoms relating to the uses and possible misuses of the substance or preparation that can reasonably be foreseen.

Kommentar [H411]: It may be necessary to mention other hazards, such as dustiness, cross-sensitisation, suffocation, freezing, high potency for odour or taste or environ-mental effects such as hazards to soil-dwelling organisms, ozone depletion, photochemical ozone creation potential, etc., which do not result in classification but which may contribute to the overall hazards of the material.





































1.	Introd	uction1
	<u>D</u> 6	efinition of Restricted Substances1
	W	hy Substances Are Restricted1
	Pu	rpose of the RSL & Why It Is Important to Suppliers1
2.	Restric	ted Substances List
3.	Where	Are the Risks?2
	Flo	owchart for Understanding Chemical Risks3
	Ba	ckground on Restricted Substances4
4.	Educat	e the Supply Chain12
5.	Labora	tory RSL Testing
6.	RSL Im	plementation
7.	Appen	<u>dices</u>
	A.	Glossary of Terms
	В.	Factory Management Plan
	C.	Model Brand Program Protocol for Testing Clothing20
	D.	Best Practices to Avoid RSL Issues
	E.	RSL Failures & Corrective Action Examples
	F.	Detailed Chemical Guidance Document31
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations32
	Н.	RSL Failure Resolution Form
	I.	Screen Printing & Applications/Finishing Best Practices
	J.	AFIRM Frequently Asked Questions (FAQ)35
	K.	Benefits of Water-Based Polyurethane47
	L.	Additional Online Resources

Appendix I – Screen Printing Best & Worst Practices







Screen print Ink Storage Best Practices

- Storage room dedicated to ink
- Room clean and free of clutter
- Shelves available to organize ink by type and keep containers off the floor
- Shelves clearly labeled
- Ink chemicals containers properly labeled
- Ink containers clean, any spills cleaned immediately
- MSDS, spill clean up equipment available



































1.	Introd	uction	1
	D	efinition of Restricted Substances	1
	W	hy Substances Are Restricted	1
	Pu	urpose of the RSL & Why It Is Important to Suppliers	1
2.	Restric	ted Substances List	2
3.	Where	Are the Risks?	2
	Fl	owchart for Understanding Chemical Risks	3
		ackground on Restricted Substances	
4.	Educat	te the Supply Chain	12
5.	Labora	itory RSL Testing	13
6.			
7.	Appen	dices	15
	A.	Glossary of Terms	16
	В.	Factory Management Plan	17
	C.	Model Brand Program Protocol for Testing Clothing	20
	D.	Best Practices to Avoid RSL Issues	
	E.	RSL Failures & Corrective Action Examples	
	F.	Detailed Chemical Guidance Document	
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations	
	Н.	RSL Failure Resolution Form	33
1	1 .	Screen Printing & Applications/Finishing Best Practices	34
	J.	AFIRM Frequently Asked Questions (FAQ)	
	K.	Benefits of Water-Based Polyurethane	
	L.	Additional Online Resources	

Appendix J – Frequently Asked Questions (FAQ)

30. Q: For the sample shown below, is a separate RSL test required for each different color, or could a composite test be performed by combining all colors?



- A: Composite testing is allowed by some AFIRM brands and not others. Brands that do allow compositing have different limits for the number of samples that may be included in a composite. This number may vary depending on the materials tested and the restricted substance tested for.
 - If composite testing is allowed, and if, for example, three is the maximum number of materials allowed for composite testing, a composite of equal amounts of the three materials can be tested. Brand policy as well as nominated laboratories will direct suppliers on composite requirements or restrictions.
- 31. Q: For an embroidered badge, can RSL testing be performed using a composite test for all colors and all different layers?
 - A: For those AFIRM brands that allow compositing, RSL testing should be performed by compositing the colors. A separate test of the adhesive layer should be performed if it is possible to separate that adhesive layer.



































1.	Introduction				
	<u>D</u>	<u>Definition of Restricted Substances</u>			
	W	/hy Substances Are Restricted	1		
	P	urpose of the RSL & Why It Is Important to Suppliers	1		
2.	Restric	cted Substances List			
3.	Where	Are the Risks?			
	<u>Fl</u>	owchart for Understanding Chemical Risks	:		
	B	ackground on Restricted Substances			
4.	Educa	te the Supply Chain	1		
5.	Labora	story RSL Testing	13		
6.	RSL Im	plementation	1		
7.	Appen	dices	15		
	A.	Glossary of Terms	16		
	В.	Factory Management Plan	17		
	C.	Model Brand Program Protocol for Testing Clothing	2(
	D.	Best Practices to Avoid RSL Issues	26		
	E.	RSL Failures & Corrective Action Examples	3(
	F.	Detailed Chemical Guidance Document	3:		
	G.	Material Safety Data Sheet (MSDS) Examples and Explanations	32		
	Н.	RSL Failure Resolution Form			
	I.	Screen Printing & Applications/Finishing Best Practices	34		
	J.	AFIRM Frequently Asked Questions (FAQ)			
	▲ K.	Benefits of Water-Based Polyurethane			
_	L.	Additional Online Resources			

Appendix L – Additional Online Resources

Appendix L—Additional Online Resources

Chemical Restriction Information

Restricted Substance Lists and Resources

AAFA Restricted Substance List

https://www.apparelandfootwear.org/Resources/RestrictedSubstances.asp

This Restricted Substances List (RSL) was created by a special working group of the American Apparel & Footwear Association's (AAFA) Environmental Task Force. The RSL is intended to provide apparel and footwear companies with information related to regulations and laws that restrict or ban certain chemicals and substances in finished home textile, apparel, and footwear products around the world. The American Apparel & Footwear Association (AAFA) is the national trade association representing apparel, footwear and other sewn products companies, and their suppliers, which compete in the global market.

AFIRM Brand Links (available on AFIRM website)

http://www.afirm-group.com/companies.htm








































Toolkit Reception

Monthly Toolkit Traffic

- July 2012 4,615
- August 2012 5,559
- September 2012 5,269
- October 2012 8,087
- November 15, 2012 HCM City, Vietnam Seminar
- November 2012 **83,583**
- December 2012 28,926







































Future Toolkit Additions?

Further additions based on Supplier feedback?

Additional ideas?







































AFIRM Toolkit Website

- http://www.afirm-group.com/supplierrsltool.htm
 - Contact: <u>info@afirm-group.com</u>







































The audio recording and slides shown during this presentation will be available to GC3 Members on the GC3 Website:

http://www.greenchemistryandcommerce.org

Non- GC3 Member Attendees who would like to view these slides please contact Sarah Shields at sarah shields@uml.edu

Space is Limited. Register Today!

http://www.greenchemistryandcommerce. org/events.roundtable.overview.php

